



File LAD981910623
LAD981910649
LAD981910631

Hatcher
BST

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION VI
ALLIED BANK TOWER AT FOUNTAIN PLACE
1445 ROSS AVENUE
DALLAS, TEXAS 75202

REPLY TO: 6W-SP

MEMORANDUM

DATE: September 11, 1987

SUBJECT: Potential Hazardous Waste Site - Site Inspection Report

FROM: Oscar Cabra, Jr., P.E. *[Signature]*
Chief
Water Supply Branch (6W-S)

TO: Martha McKee
Chief
Superfund Compliance Section (6H-ES)

In response to the CERCLA investigation reports which you recently sent to the Water Supply Branch, I am attaching our comments. Thank you for the opportunity to review these documents.

Attachments: Sutton Joint Account #1 & #2
Hackberry, LA
LAD981910623 (#1)
~~LAD981910649 (F. Lacy Lease)~~
LAD981910631

cc: Carl Hickam (6H-ES)

SUPERFUND
FILE

JUL 17 1992

REORGANIZED

90069354



REVIEW

Potential Hazardous Waste Site - Inspection Report

Site Name Sutton Joint Account #1 + 2

Site Location 14. 11. 24

Site Number #2-7000-11111 Date of Survey _____

Inspected by _____ State FIT TAT _____

Other (specify) _____

Received From Hatchee

Date rec'd by Water Supply Branch 1/20/84

Type samples:

<input type="checkbox"/> on-site	<input type="checkbox"/> on-site	<input type="checkbox"/> on-site	<input type="checkbox"/> on-site
<input type="checkbox"/> SOIL	<input type="checkbox"/> SURFACE WATER	<input type="checkbox"/> GROUND WATER	<input type="checkbox"/> DRINKING WATER
<input type="checkbox"/> off-site	<input type="checkbox"/> off-site	<input type="checkbox"/> off-site	<input type="checkbox"/> off-site

Type contaminant(s):

☐ ORGANICS ☐ INORGANICS ☐ RADIONUCLIDES ☐ MICROBIOLOGICAL

Summary:

AGREE WITH RECOMMENDATION THAT NO FURTHER ACTION BY FIT BE TAKEN, BUT THAT THE APPROPRIATE AGENCY BE ADVISED OF ANY ACTION THAT NEEDS TO BE TAKEN AS RECOMMENDED BY FIT DURING THE 5-27-83 INSPECTION REPORT. THE APPROPRIATE AGENCY BEING THE U.S. COAST GUARD IN THIS CASE.

THE FOLLOWING REPORTS ARE INCLUDED WITH THE SAME RECOMMENDATION:

EE LACY LEASE - LAD 981910649
SUTTON JOINT ACC. #2 - LAD 981910631
SUTTON JOINT ACC. #1 - LAD 981910623

Concurrence:

C. P. Brown for C 9/9/87

Jose Y Rodriguez 9-8-87
Signature and Date



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

06

SITE NUMBER

LAO 981910649

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME Lacy Lease		B. STREET (or other identifier) 0.6 mi. North of LA Hwy 390 and 0.3 mi. West of LA Hwy 27	
C. CITY Hackberry	D. STATE LA	E. ZIP CODE 70643	F. COUNTY NAME Cameron 023
G. OWNER/OPERATOR (if known) 1. NAME Mrs. Frances Heirs Lacy c/o Miss Lennie Lacy 4217 Waterwood Drive, Lake Charles, LA 70605			
2. TELEPHONE NUMBER			

H. TYPE OF OWNERSHIP (if known)					
<input type="checkbox"/> 1. FEDERAL	<input type="checkbox"/> 2. STATE	<input type="checkbox"/> 3. COUNTY	<input type="checkbox"/> 4. MUNICIPAL	<input checked="" type="checkbox"/> 5. PRIVATE	<input type="checkbox"/> 6. UNKNOWN

I. SITE DESCRIPTION 29°59'40"N 93°22'12"W 0.25 acre site is an active petroleum well with a pump and one storage tank. See "CAM 54", Browns Lake topo map
--

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) Aerial photographs and FIT windshield survey	K. DATE IDENTIFIED (mo., day, & yr.) 2-17-87
--	---

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM Diking is inadequate around both the well and the storage tank. Petroleum and salt water are migrating off site via the adjacent drainage ditch, as evidenced by the dead vegetation, black oily residue, and white crust in the ditch.

SUPERFUND
FILE

JUL 17 1992

REORGANIZED

Reviewed by SH-ES
Date 7/23/92

M. PREPARER INFORMATION		
1. NAME R. David Shiels/JoAnn T. Weber	2. TELEPHONE NUMBER (214) 742-6601	3. DATE (mo., day, & yr.) 2-23-87